

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

No 348593

DO NOT USE INK.

Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

County Williams Township Springfield Section of Township 18
Owner Wayne Carlin Address RR 2 Stryker Ohio
Location of property 1 1/2 west of Stryker, Ohio on RR 2

CONSTRUCTION DETAILS

Casing diameter 4 Length of casing 137
Type of screen Coar Length of screen 3
Type of pump Sub
Capacity of pump 14
Depth of pump setting 100
Date of completion Dec 10 - 67

BAILING OR PUMPING TEST

Pumping Rate.....G.P.M. Duration of test.....hrs.
Drawdown.....ft. Date.....
Static level-depth to water 20 ft.
Quality clear (cloudy, taste, odor).....
Pump installed by Stanley Graf

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Top soil</u>	<u>0 Feet</u>	<u>1 Ft.</u>
<u>yellow clay</u>	<u>1</u>	<u>9</u>
<u>blue clay</u>	<u>9</u>	<u>70</u>
<u>hard pan</u>	<u>70</u>	<u>110</u>
<u>Clay</u>	<u>110</u>	<u>122</u>
<u>hard pan</u>	<u>122</u>	<u>132</u>
<u>gravel</u>	<u>132</u>	<u>137</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.

S.

See reverse side for instructions

Drilling Firm Stanley Graf
Address Archbold Ohio

Date Dec 10 - 67
Signed Stanley Graf

*If additional space is needed to complete well log, use next consecutive numbered form.

(31) (2)