

WELL-LOG AND DRILLING REPORT

ORIGINAL

TICK HOLLAND

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No. 353785

177

County Scioto Township Vernon Section of Township EASTERN
Owner John Clark Address WHEELERSBURG, D.
Location of property SHELTON RD. 1/2 MI. S. OF LICK RUN RD.

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing.....
Type of screen..... Length of screen.....
Type of pump DW
Capacity of pump.....
Depth of pump setting.....
Date of completion 4-9-69

BAILING OR PUMPING TEST


Pumping Rate 1 G.P.M. Duration of test 4 hrs.
Drawdown 30' ft. Date 4-9-69
Static level-depth to water 30' ft.
Quality (clear, cloudy, taste, odor).....
Pump installed by Clark

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>DIRT</u>	<u>0 Feet</u>	<u>15 Ft.</u>
<u>Shale</u>	<u>15'</u>	<u>40'</u>
<u>SANDSTONE</u>	<u>40'</u>	<u>55'</u>
<u>Shale</u>	<u>55'</u>	<u>60'</u>
<u>Water</u>		
<u>AT</u>		
<u>40'</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Hargis Hughes
Address Rt 2 PORTS O.

Date 4-9-69
Signed Hargis Hughes

*If additional space is needed to complete well log, use next consecutive numbered form.

18