

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

No 356846

DO NOT USE INK.

Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

County INOX Township Jackson Section of Township 1st Sec 2
Owner Ely J. S. Miller Address Howard Ohio
Location of property Dennis Church Rd 1.1 mile, west of Co. Rd 38

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 43.8
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 12 G.P.M. Duration of test 1 hrs.
Drawdown 4 ft. Date 10-12-79
Static level-depth to water 16' ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>DR. & clay</u>	<u>0 Feet</u>	<u>22 Ft.</u>
<u>Gray shale</u>	<u>22</u>	<u>30</u>
<u>Brown Sand stone</u>	<u>30</u>	<u>34</u>
<u>Gray sandy shale</u>	<u>34</u>	<u>53</u>
<u>Gray Sand stone</u>	<u>53</u>	<u>59</u>
<u>water</u>	<u>40</u>	<u>59</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



S.
See reverse side for instructions

Drilling Firm Burch well Drilling Date 10-15-79
Address Box 9, Berdensburg Signed Jennie J. Burch

*If additional space is needed to complete well log, use next consecutive numbered form.