

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No 356887

County OTTAWA Township POT-1-N-BAY Section of Township N.W.
Owner C. JARMONOWICZ Address 5586 Dalewood Ave
Maple Heights, Ohio
Location of property N. End of Mitchell Ave 44137

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 28'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion AUG. 27, 1971

BAILING OR PUMPING TEST

Pumping Rate 10 G.P.M. Duration of test 2 hrs.
Drawdown 4 ft. Date 8/27/71
Static level-depth to water 30 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Limestone</u>	<u>0 Feet</u>	<u>23 Ft.</u>
<u>Dolomite</u>	<u>23</u>	<u>60</u>
<u>Light Vein</u> <u>IN CREVICE</u>	<u>60</u>	
<u>Tyngtree</u>	<u>60</u>	<u>70</u>
<u>Water</u>	<u>70</u>	
<u>Dolomite</u>	<u>70</u>	<u>74</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

LAKE Erie
West Shore
Mitchell
Ave
X
W. E.
Catawba Ave
S.
See reverse side for instructions

Drilling Firm Island Well Drilling Date 8/30/71