

WELL LOG AND DRILLING REPORT

ORIGINAL


PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No 356893

County CHANDLER Township Middle Bass Section of Township WEST
Owner HENRY MESENBURG Address 1415
Location of property Milton, O.

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>5 3/4</u> Length of casing <u>13</u>	Pumping Rate <u>4</u> G.P.M. Duration of test <u>3</u> hrs.
Type of screen _____ Length of screen _____	Drawdown <u>140</u> ft. Date <u>Aug. 20, '72</u>
Type of pump _____	Static level-depth to water <u>10</u> ft.
Capacity of pump _____	Quality (clear, cloudy, taste, odor) <u>Clear</u>
Depth of pump setting _____	Pump installed by _____
Date of completion _____	

WELL LOG*			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc. N. 
	0 Feet	1 Ft.	
<u>chry</u>			
<u>limestone</u>	<u>1</u>	<u>16</u>	
<u>dol.</u>	<u>16</u>	<u>32</u>	
<u>ti. light sand</u>	<u>32</u>	<u>33</u>	
<u>dol.</u>	<u>33</u>	<u>60</u>	
<u>WATER</u>			

Drilling Firm ISLAND WELL DRILLING Date Aug. 21, 1972
Address PO Box 213 Signed Mark Messie
Put-in-Bay, O.