

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No 358412

County LUCAS Township SYLVANIA Section of Township _____

Owner RALPH J. MOROSKI Address RT#1 - HOLT RD. SYLVANIA, OHIO

Location of property SOUTH OF BRINT RD. ON HOLT RD.

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 31'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion AUG. 17, 1967

BAILING OR PUMPING TEST


Pumping Rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date _____
Static level-depth to water 14 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>YELLOW CLAY</u>	<u>0 Feet</u>	<u>11 Ft.</u>
<u>BLUE CLAY</u>	<u>11 "</u>	<u>30 "</u>
<u>SAND</u>	<u>30 "</u>	<u>31 "</u>
<u>BLACK SHALE</u>	<u>31 "</u>	<u>55 "</u>
<u>WATER AT 31 FT.</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm GERARD BETTINGER

Address RT#1 - Box 67 BERKEY, OHIO

Date 9-7-67

Signed G. Bettinger

*If additional space is needed to complete well log, use next consecutive numbered form.

LOCATED

233