

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

No 361189

DO NOT USE INK.

Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

County Belmont Township Pultrney Section of Township 5

Owner Jane B. Riggs Address Cellaire RD #1

Location of property 2 1/2 mi. WEST OF OHIO RIVER ALONG ST RT 147 + TR 302

CONSTRUCTION DETAILS

Casing diameter 6 1/2 Length of casing 26
Type of screen _____ Length of screen _____
Type of pump Sub.
Capacity of pump 8 GPM
Depth of pump setting 25
Date of completion 12-15-70

BAILING OR PUMPING TEST

Pumping Rate 8 G.P.M. Duration of test _____ hrs.
Drawdown none ft. Date _____
Static level-depth to water 18 ft.
Quality (clear, cloudy, taste, odor) Sulfur
Pump installed by B.B. Cult

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
<u>clay</u>	<u>1</u>	<u>7</u>
<u>Sandstone</u>	<u>7</u>	<u>17</u>
<u>clay shale</u>	<u>17</u>	<u>18</u>
<u>Slate</u>	<u>18</u>	<u>20</u>
<u>Limestone</u>	<u>20</u>	<u>30</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.



S.

See reverse side for instructions

Drilling Firm B.B. Cult

Date 12-1 1970

Address 3101 Clinton St
Cellaire O

Signed B.B. Cult

*If additional space is needed to complete well log, use next consecutive numbered form.

120