

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

Division of Water

1562 W. First Avenue

Columbus, Ohio 43212

Nº 361194

County Rehoboth Township Pultney Section of Township 7

Owner Tom Myers Address Bellevue Rd 2

Location of property along Co. Road #3 at Moss Run 2 MI WEST of Bellevue

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 37

Type of screen Length of screen

Type of pump jet

Capacity of pump

Depth of pump setting 32

Date of completion July 10 1971

BAILING OR PUMPING TEST

Pumping Rate 3 G.P.M. Duration of test hrs.

Drawdown ft. Date

Static level-depth to water 14' ft.

Quality (clear, cloudy, taste, odor) clear

Pump installed by owner

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

Ft.

Clay

1

6

Sand & Gravel

6

18

Shale

18

21

Clay

21

31

Sandstone


31

37

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.



S.

See reverse side for instructions

Drilling Firm

R.B. Dault

Date

July 10 1971