

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No. 362389

County Lawrence Township Elizabeth Section of Township 28

Owner Gorge Mullins Address R3 Ironton Ohio

Location of property Pine Creek Road off SR 93

CONSTRUCTION DETAILS

Casing diameter 5/8 Length of casing 13

Type of screen _____ Length of screen _____

Type of pump _____

Capacity of pump _____

Depth of pump setting _____

Date of completion _____

BAILING OR PUMPING TEST

Pumping Rate 1 G.P.M. Duration of test 3 hrs.

Drawdown _____ ft. Date _____

Static level-depth to water _____ ft.

Quality (clear, cloudy, taste, odor) cloudy


Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.
<u>clay</u>		<u>12</u>
<u>Slate Rock</u>		<u>28</u>
<u>Lime Stone</u>		<u>42</u>
<u>Slate Rock</u>		<u>76</u>
<u>Slate & shell</u>		<u>104</u>
<u>water 102-104</u>		<u>130</u>
<u>1 gal pm</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



S.

See reverse side for instructions

Drilling Firm Spear S

Date 10 31 68

Address Ironton O

Signed Samuel E. Spears

*If additional space is needed to complete well log, use next consecutive numbered form.