

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No 365513

County Ottawa Township Barbours Section of Township _____
Owner Kenneth Johnson Address 1833 Post Rd. Mansfield, Ohio
Location of property Snag Harbor - Bay Shore Rd.

CONSTRUCTION DETAILS

Casing diameter 5 7/8" Length of casing 20' 11"
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting 49'
Date of completion Oct 2, 1967

BAILING OR PUMPING TEST


Pumping Rate 2 G.P.M. Duration of test 1 hrs.
Drawdown 45 ft. Date Oct 2, 1967
Static level-depth to water 6 ft.
Quality (clear, cloudy, taste, odor) sa/fer
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Yellow Clay</u>	<u>0 Feet</u>	<u>6 Ft.</u>
<u>Hard limestone</u>	<u>6</u>	<u>52</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Tibbales Well Drilling Date Oct 2, 1967
Address 435 Elliot Ave. Bellefonte Signed W. J. Tibbales