

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

OK - Sub
 N: 367285

Location of property ON ST RT 7 NORTH OF CLARINGTON

BAILING OR PUMPING TEST

Date of completion.....2.25.67

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

Soil

0 Feet

10 Ft.

SAND & GRAVEL

20

72

Gray Shale

72

75

Lime Stone

75

76

WATER 40

W.

WELL

↑
O
M
P
M
P

N.

CLAREINGTON

See reverse side for instructions

Drilling Firm Edwards Drilling Co

Date 3-7-69

1983