

WELL LOG AND DRILLING REPORT

ORIGINAL

(43)

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No. 368434

6797A

County CARROLL Township MON ROE Section of Township 33

Owner GEORGE BURRIS Address 5297 ANTIGUA RD

Location of property LEVITTSVILLE SW SHERDSVILLE OHIO

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 30'
Type of screen NO SCREEN Length of screen _____
Type of pump SUBMERGIBLE
Capacity of pump 5 GAL NINUTE
Depth of pump setting 107'
Date of completion 7-28-1973

BAILING OR PUMPING TEST


Pumping Rate 3 G.P.M. Duration of test 1 hrs.
Drawdown 39 ft. Date 7-28-1973
Static level-depth to water 42 ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by NEELY DRILLING

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>DIRT</u>	<u>0 Feet</u>	<u>3 Ft.</u>
<u>BLACK SLATE</u>	<u>3</u>	<u>19</u>
<u>BROWN SAND</u>	<u>19</u>	<u>34</u>
<u>GRAY SAND</u>	<u>34</u>	<u>64</u>
<u>BLACK SLATE</u>	<u>64</u>	<u>75</u>
<u>FIRE CLAY</u>	<u>75</u>	<u>78</u>
<u>GRAY SLATE</u>	<u>78</u>	<u>82</u>
<u>RED ROCK</u>	<u>82</u>	<u>85</u>
<u>LIME STONE</u>	<u>85</u>	<u>88</u>
<u>FIRE CLAY</u>	<u>88</u>	<u>98</u>
<u>LIME STONE</u>	<u>98</u>	<u>113</u>
<u>GRAY SAND</u>	<u>113</u>	<u>120</u>
<u>WATER AT 45'</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm NEELY DRILLING

Date 8/14/1973

Address 5060 PICADOR RD SE

Signed KENNETH NEELY

(170)

*If additional space is needed to complete well log, use next consecutive numbered form.