

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCESDivision of Water
1562 W. First Avenue
Columbus, Ohio 43212

No 368435

County CARROLL Township EAST Section of Township 1Owner FRED WALTER Address RDI KENSINGTONLocation of property 2 MILES SOUTH WEST OF KENSINGTON

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 30'

Type of screen _____ Length of screen _____

Type of pump SUBMERGIBLECapacity of pump 245 GALLONS / HRDepth of pump setting 87'Date of completion 8, 20, 1973


BAILING OR PUMPING TEST

Pumping Rate 15 G.P.M. Duration of test 1 hrs.Drawdown 20 ft. Date _____Static level-depth to water 50 ft.Quality (clear, cloudy, taste, odor) CLEARPump installed by NEELY DRILLING

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>CLAY</u>	<u>0 Feet</u>	<u>8 Ft.</u>
<u>SHALE</u>	<u>8</u>	<u>20</u>
<u>GRAY SLATE</u>	<u>20</u>	<u>32</u>
<u>GRAY SAND</u>	<u>32</u>	<u>59</u>
<u>BROWN SAND</u>	<u>59</u>	<u>82</u>
<u>GRAY SAND</u>	<u>82</u>	<u>100</u>
<u>WATER AT 50'</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

See reverse side for instructions

Drilling Firm NEELY DRILLINGDate 8, 12, 1973Address PICADOR ROAD SOUTHEASTSigned KENNETH NEELY

*If additional space is needed to complete well log, use next consecutive numbered form.