


ORIGINAL

Nº 370206

Location of property 1/4 mile South of Mells Rd. on Stanhope-Kelloggsville Road

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST	
Casing diameter <u>6"</u>	Length of casing <u>37'</u>		Pumping Rate <u>30</u> G.P.M.	Duration of test <u>12</u> hrs.
Type of screen _____	Length of screen _____		Drawdown <u>20</u> ft.	Date <u>10-4-68</u>
Type of pump _____			Static level-depth to water <u>4</u> ft.	
Capacity of pump _____			Quality (clear, cloudy, taste, odor) <u>clear</u>	
Depth of pump setting _____			Pump installed by <u>None (Bailing Test)</u>	
Date of completion <u>10-4-68</u>				
WELL LOG*			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
<u>Clay</u>	<u>0 Feet</u>	<u>11 Ft.</u>	 <u>Stanhope Kelloggsville Rd. N.</u> <u>W. Mells Rd.</u> Well E.	
<u>Sandy soft Shale</u>	<u>11</u>	<u>34</u>		
<u>Shale</u>	<u>34</u>	<u>45</u>		
<u>Water at 40'</u>				
				

Date 10-4-68

Signed Carl W Burns

*If additional space is needed to complete well log, use next consecutive numbered form.