

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

DO NOT USE INK.

Owner Dr. J. L. Haver Address R.R. 5, Wash.

Location of property at Intersect of Bt O R R and RT 30-343 (1238)

BAILING OR PUMPING TEST

Pumping Rate 15 G.P.M. Duration of test 1 hrs.

Drawdown 3 ft. Date Sept 24, 1968

Static level-depth to water 22 ft.

Quality (clear, cloudy, taste, odor).....

Pump installed by.....

Pump installed by.....

SKETCH SHOWING LOCATION

From

To

0 Feet

10 Ft.

clay

Bolden

10

14

Sandy Clary

14

4.

Bulder

4.

4-

Land & House

43

725

N.

238 SR 38

W.

E

S.

See reverse side for instructions

Drilling Firm McCoy Well Drilling

Date Sept 24 / 1968

Address Wash etl

Signed A. M. G. W.

*If additional space is needed to complete well log, use next consecutive numbered form.

130.3