

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

No 372181

Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

DO NOT USE INK.

County Delaware Township Pelee Section of Township delaware
Owner Harry Alltop Address 808 W. 11th St. Sarnia
Location of property on city rd 620 1/2 mile East Sarnia

CONSTRUCTION DETAILS

Casing diameter 4 1/2 Length of casing 104
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion Oct 1 - 1969

BAILING OR PUMPING TEST

Bailing
Pumping Rate 5 G.P.M. Duration of test 1 hrs.
Drawdown 50 ft. Date Oct 1 - 1969
Static level-depth to water 40 ft.
Quality (clear, cloudy, taste, odor) clear
no odor
Pump installed by _____

WELL LOG*

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

6 Ft.

clay
slate

6

25

gravel

25

72

sand

72

94

shale (red)

94

104

shale (red)

104

133

water 104 - 106

126 130

Total 104 to 133 1/4

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.

S.

See reverse side for instructions

1111
94

1117

Drilling Firm

Harry Alltop

Date

Oct 1 - 1969

Address

808 W. 11th St. Sarnia

Signed

Harry Alltop

*If additional space is needed to complete well log, use next consecutive numbered form

LOCATED
29