

WELL LOG AND DRILLING REPORT

ORIGINAL

71 ✓

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 375099

County VINTON Township ELK Section of Township 22

Owner PAUL MORGAN Address RED McARTHUR, OH 45651

Location of property ON ELK TWP RD 11 1/4 M NORTH OF R 50E ON MORGAN RD

CONSTRUCTION DETAILS

Casing diameter 7" 00 Length of casing 11' 4"
Type of screen 5 1/2" 00 Length of screen 198'
Type of pump SUBMERSIBLE
Capacity of pump 1 HP
Depth of pump setting 184'
Date of completion AUG 6, 1974

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 15 G.P.M. Duration of test hrs.
Drawdown ALL ft. Date AUG 6, 1974
Static level-depth to water 40 ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by GEORGE L. TURNER

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>TOPSOIL</u>	<u>0 Feet</u>	<u>1 Ft.</u>
<u>SUBSOIL</u>	<u>1</u>	<u>10</u>
<u>SANDSTONE</u>	<u>10</u>	<u>18</u>
<u>SHALE, GRAY</u>	<u>18</u>	<u>67</u>
<u>COAL</u>	<u>67</u>	<u>67 1/2</u>
<u>SHALE, GRAY</u>	<u>67 1/2</u>	<u>98</u>
<u>LIME</u>	<u>98</u>	<u>188</u>
<u>SAND, WHITE</u>	<u>188</u>	<u>206</u>
<u>WATER AT 67 1/2 FT BAD</u>		
<u>CASED OFF</u>		
<u>WATER AT 200 FT</u>		
<u>RUN 5 1/2" PIPE 196' AND</u>		
<u>CEMENTED IN WITH 3 SACKS</u>		
<u>CEMENT</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm GEORGE L. TURNER

Date AUG 9, 1974

Address NEW PLYMOUTH

Signed Geo L Turner

OHIO 45654

*If additional space is needed to complete well log, use next consecutive numbered form.