

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 377043

County Harrison Township Stock Section of Township _____
Owner Adam Harp Address Bellaire, Ohio
Location of property Tappan Lake 1/4 mile N of U.S. 250

CONSTRUCTION DETAILS

Casing diameter 4 1/2" Length of casing 46' 5"
Type of casing 6 3/4" I.D. Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 60 G.P.M. Duration of test 2 hrs.
Drawdown None ft. Date 8-12-71
Static level-depth to water 33' ft.
Quality (clear, cloudy, dirty, taste, no odor) _____
Pump installed by owner

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From Feet	To Ft.
yellow clay	12'	12'
Gray Slate	6'	18'
Shale, sandy	4'	22'
Lime Stone	3'	25'
Shale Sandy	5'	30'
Sand Stone	5'	35'
Sand Stone	5'	40'
Shale Sandy	5'	45'
Sand Stone	10'	55'
DRY Mate	11'	66'
Sand Stone	4'	70'

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Floyd H. Lamb
Address Bellaire, O. P.O. Box 43907

Date 8-12-1971
Signed F. H. Lamb

*If additional space is needed to complete well log, use next consecutive numbered form.