

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 377742

County Porter Township Bancroft Section of Township _____
Owner Thomas Egan Address 1006 Belding Rd
Bancroft, O.
Location of property _____

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 58.8
Type of screen _____ Length of screen _____
Type of pump Deep well
Capacity of pump 9 P.M.
Depth of pump setting 40
Date of completion Jan 25 1969

BAILING OR PUMPING TEST (Specify one by circling)

Test Rate 25 G.P.M. Duration of test _____ hrs.
Drawdown 3 ft. Date Jan 25 1969
Static level-depth to water 29 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Carl F. Peterson

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>21 Ft.</u>
<u>Sand</u>	<u>21</u>	<u>28</u>
<u>Blue clay</u>	<u>28</u>	<u>41</u>
<u>Sand</u>	<u>41</u>	<u>46</u>
<u>Sandstone</u>	<u>46</u>	<u>55</u>
<u>Sandstone</u>	<u>55</u>	<u>58</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.
W. E.
S.
Wetzel
2524
Alexander
St 44
Eddy
Belding

Drilling Firm Carl F. Peterson

Date Jan 25 1969