

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 377744

County Mahoning Township Milton Section of Township
Owner Orrel Stine Address Whisper Lake Milton
Location of property Zone

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 76 1/2
Type of screen Length of screen
Type of pump Deep Well
Capacity of pump
Depth of pump setting 20
Date of completion Feb 28 1969

BAILING OR PUMPING TEST (Specify one by circling)

Test Rate 20 G.P.M. Duration of test hrs.
Drawdown 1 ft. Date Feb 28 1969
Static level-depth to water 38 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>26 Ft.</u>
<u>Sandstone</u>	<u>26</u>	<u>35</u>
<u>Blue Clay</u>	<u>35</u>	<u>70</u>
<u>Shale</u>	<u>70</u>	<u>74</u>
<u>Gray shale</u>	<u>74</u>	<u>130</u>
<u>Sandstone</u>	<u>130</u>	<u>146</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N. Elev. of Rock = 910

RT 18

W.

E.

S.

Drilling Firm Capt. H. P. Peltzman
Address 52 S. Main St. Milton

Date
Signed Capt. H. P. Peltzman

36
LOCATED

*If additional space is needed to complete well log, use next consecutive numbered form.