

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 379033

County Trumbull Township Champion Section of Township West central
Owner Robert Ulan Address Oakhill Drive Warren
Location of property 2 1/2 Miles west 3/4 mi north of Champion

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 78
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 20 G.P.M. Duration of test 3 1/2 hrs.
Drawdown 13 ft. Date Sept 26th 69
Static level-depth to water 12 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>20 Ft.</u>
<u>Clay + sand</u>	<u>20</u>	<u>55</u>
<u>Clay</u>	<u>55</u>	<u>70</u>
<u>Shale gray</u>	<u>70</u>	<u>80</u>
<u>Shale black</u>	<u>80</u>	<u>87</u>
<u>White sand</u>	<u>87</u>	<u>95</u>
<u>Water at 90 ft.</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm David F. Gephart
Address 386 Champion & Bristol Rd
Warren

Date Sept 26th '69
Signed David F. Gephart

*If additional space is needed to complete well log, use next consecutive number

