

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 383059

County COSHOCTON Township KEENE Section of Township SOUTH WEST

Owner JACK MCNEAL Address 1624 E VINE ST COSHOCTON

Location of property ON STATE ROUTE 621 5 MILE NORTH OF COSHOCTON

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 12

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST (Specify one by circling)

Test Rate 20 G.P.M. Duration of test 2 hrs.

Drawdown 20 ft. Date 12-3-68

Static level-depth to water 35 ft.

Quality (clear, cloudy, taste, odor) CLEAR

Pump installed by OWNER

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>CLAY</u>	<u>0 Feet</u>	<u>8 Ft.</u>
<u>SHALE</u>	<u>8</u>	<u>18</u>
<u>FLINT ROCK</u>	<u>18</u>	<u>25</u>
<u>SHALE</u>	<u>25</u>	<u>36</u>
<u>LIMESTONE</u>	<u>36</u>	<u>42</u>
<u>SHALE</u>	<u>42</u>	<u>68</u>
<u>WATER AT 36'</u>		
<u>" " 54'</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

24278

N.

W.

E.

S.

STATE ROUTE 621
WELL
STATE ROUTE 16-36

Drilling Firm MENICHOS AND SON Date 12-4-68

Address RT 1 ADAMSVILLE OHIO Signed J. MENICHOS

*If additional space is needed to complete well log, use next consecutive numbered form.