WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 383371

OK

County Morrow Township Bennington Section of Township

Owner Oscar L. Coy Address Rt. 1, Box 2, Mareuga, Ohio

Location of property Co Rd 21 E of Co Rd 26 - Cross RR tracks, 2nd blue on left

CONSTRUCTION DETAILS

Casing diameter 4 1/2 OD Length of casing 42'

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion 8-10-69

BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 9 G.P.M. Duration of test 1 hrs.

Drawdown 5 ft. Date

Static level-depth to water 8' ft.

Quality (clear, cloudy, taste, odor) clear

Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Top Soil	0 Feet	1 Ft.
Brown Clay	1'	42'
Gray Shale	42'	47'

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



Drilling Firm Blanton Supply Date 12-15-69

Address R2, Mt. Gilead O Signed Dorothy Blanton

16

*If additional space is needed to complete well log, use next consecutive numbered form.