

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

OK

County Norfolk Township Burnington Section of Township _____
Owner James John Address Rt. 1, Marengo, Ohio
Location of property C. Rd. 21 E. of C. Rd. 26 - Cross Rd. - 2nd house on right

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST (Specify one by circling)
Casing diameter <u>4 1/2" OD</u> Length of casing <u>90'</u>	Test Rate <u>9</u> G.P.M. Duration of test <u>2</u> hrs.
Type of screen <u>—</u> Length of screen <u>—</u>	Drawdown <u>20</u> ft. Date <u>—</u>
Type of pump <u>—</u>	Static level-depth to water <u>25'</u> ft.
Capacity of pump <u>—</u>	Quality (clear, cloudy, taste, odor) <u>taste, odor,</u>
Depth of pump setting <u>—</u>	<u>cloudy (Black Sulphur)</u>
Date of completion <u>8-18-69</u>	Pump installed by <u>other</u>

[illegible]

Drilling Firm Blanton Supply
Address R. 2, Mt. Gilead O

Date 12-15-69
Signed Dorothy Blanton (17)
11 log. use next consecutive numbered form.

*If additional space is needed to complete well log, use next consecutive numbered form.