WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 383690

County MORGAN Township MALTA Section of Township

Owner DELBERT ROBERTS Address McCONNELLSVILLE O. R#4

Location of property 1/2 MI N OF MALTA ON LEFT SIDE OF SR 669

CONSTRUCTION DETAILS

Casing diameter 5 & 1D Length of casing 32-6

Type of screen PERF CASING Length of screen 3-0

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 20 G.P.M. Duration of test 1/2 hrs.

Drawdown 5-0 ft. Date 10-23-72

Static level-depth to water 9-0 ft.

Quality (clear, cloudy, taste, odor) CLEAR.

Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
SURFACE	0 Feet	4-0 Ft.
SAND & DRIFT	4-0	18-0
SAND & GRAVEL	18-0	32-0
TOTAL DEPTH	32-0	
WATER AT 27-0		

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



Drilling Firm TUTHILL DRILLING SERVICE Date 10-23-72

Address STOCKPORT OHIO R#2 43787 Signed R. E. Tuthill

*If additional space is needed to complete well log, use next consecutive numbered form.