

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

NO. 384565

County Sandusky Township Sandusky Section of Township 15
Owner E. Lester L. Belcher Address Germantown, Ohio
Location of property On St. Rt. #53. 1 mi. North of U.S. 20 By. Pass

CONSTRUCTION DETAILS

Casing diameter 4 1/4" Length of casing 69'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)

Test Rate _____ G.P.M. Duration of test _____ hrs.
Drawdown none ft. Date _____
Static level-depth to water 31' ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Loam</u>	<u>0 Feet</u>	<u>4' Ft.</u>
<u>Shale</u>	<u>4'</u>	<u>42'</u>
<u>Sand</u>	<u>42'</u>	<u>53'</u>
<u>Broken limestone</u>	<u>53'</u>	<u>69'</u>
<u>limestone</u>	<u>69'</u>	<u>81'</u>
<u>Good water</u>		


SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

2720 C.R. 53 N.

W. U.S. Rt. #20

E.



Drilling Firm M & G. well Drilling

Date Sept. 14 / 68

Address 712 - O'Donnell St.

Signed Carol E. Green

Upper Sandusky, Ohio

*If additional space is needed to complete well log, use next consecutive numbered form.

37

38