

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 384659

County Portage Township Brimfield Section of Township _____
Owner William A. Hastler Address 3748 Martha Rd Kent
Location of property One mile south of Brimfield off 43

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 59
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 10 G.P.M. Duration of test 3 hrs.
Drawdown _____ ft. Date 3/15/69
Static level-depth to water 15 ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>15 Ft.</u>
<u>Clay + Gravel</u>	<u>15</u>	<u>45</u>
<u>Sand + Gravel</u>	<u>45</u>	<u>56</u>
<u>Shale</u>	<u>56</u>	<u>67</u>
<u>Well</u>	<u>67 ft</u>	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Suburban Pump Co Date March 15 / 1969
Address 1806 Sandy Lake Rd Ravenna Signed Galigh Basinger

*If additional space is needed to complete well log, use next consecutive numbered form.