ORIGINAL

WELL LOG AND DRILLING REPORT

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 385648

County Wayne Township Milton Section of Township 34

Owner Gene Homan Address Marshallville, O-R#1

Location of property

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 35'

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion 11-1-72

BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 15 G.P.M. Duration of test 2 hrs.

Drawdown 2 ft. Date 11-1-72

Static level-depth to water 77 ft.

Quality (clear, cloudy, taste, odor)

Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Soil & Clay	0 Feet	15 Ft.
Gray Sandy Shale	15	35
Blue Shale & Rock	36	80
Gray Sandstone	80	130
Blue Shale	130	137

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



Drilling Firm Reynolds Drilling Co. Date 11-17-72

Address R.D. #2 Orrville, O. Signed B.A. Reynolds

*If additional space is needed to complete well log, use next consecutive numbered form.

384