

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 391031

County Lucas Township Springfield Section of Township 18
Owner Richard Inderrieden Address 9005 Angola Rd. Cridsey, O
Location of property 1/8 Mile E of Cridsey Rd on Angola Rd

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 50'
Type of screen None Length of screen _____
Type of pump Submersible
Capacity of pump 10 GPM
Depth of pump setting 40
Date of completion 5-10-69

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 10 G.P.M. Duration of test 1 hrs.
Drawdown 5 ft. Date 5-10-69
Static level-depth to water 6 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Larson Drilling & Mach Inc

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Yellow Sand</u>	<u>0 Feet</u>	<u>15 Ft.</u>
<u>Grey Water Sand</u>	<u>15</u>	<u>50</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Larson Drilling & Mach Inc
Address 211 W. Sophia St. Maumee, O

Date 5-10-69

Signed Cliff Overman

81

*If additional space is needed to complete well log, use next consecutive numbered form.