

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 393951

County LUCAS Township MONCLOVA Section of Township 32

Owner MR. & MRS. JOHN - P. CHAPMAN Address 8004 - MAUMEE - WESTERN RD.

Location of property 1/10 MILE EAST OF ALBON - NORTH OF MAUMEE WESTERN RD.

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 18.6"
Type of screen NONE Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 10 G.P.M. Duration of test 2 hrs.
Drawdown 24 ft. Date MARCH 8 - 1971
Static level-depth to water 6' ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>SAND</u> <u>YELLOW & BROWN</u>	<u>0 Feet</u>	<u>6 Ft.</u>
<u>BLUE CLAY</u>	<u>6'</u>	<u>14'</u>
<u>HARD PAN</u>	<u>14'</u>	<u>17' 10"</u>
<u>BROWN - LIME HARD</u>	<u>17'</u>	<u>25'</u>
<u>BROWN & GRAY - LIME</u>	<u>25'</u>	<u>34'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm BOB LARSON - DRILLING Date 3/11/71
Address 4038 - ALBON RD. - MONCLOVA Signed Bob Larson

*If additional space is needed to complete well log, use next consecutive numbered form.

(62A)