

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 393956

County LUCAS Township MONCLOVA Section of Township 31

Owner MR. & MRS. RAYMOND BLANCHARD Address 1149 KIRK ST. MAUMEE - OHIO

Location of property BETWEEN - CRISSEY RD AND WRECKERLY RD. ON SAUSBURY.

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST (Specify one by circling)	
Casing diameter <u>4 1/4</u>	Length of casing <u>58'</u>		Test Rate <u>20</u> G.P.M.	Duration of test <u>3</u> hrs.
Type of screen	Length of screen		Drawdown <u>10'</u> ft.	Date <u>JUNE - 18 - 1971</u>
Type of pump			Static level-depth to water <u>13'</u> ft.	
Capacity of pump			Quality (clear, cloudy, taste, odor) <u>CLEAR</u>	
Depth of pump setting				
Date of completion			Pump installed by	

WELL LOG*			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
<u>YELLOW SANDY CLAY</u>	<u>0 Feet</u>	<u>13 Ft.</u>	N. E. W. S.	
<u>GRAY & BLUE CLAY</u>	<u>13</u>	<u>35'</u>		
<u>HARD - PAN</u>	<u>35'</u>	<u>47'</u>		
<u>BLACK - SAND</u>	<u>47'</u>	<u>53'</u>		
<u>GRAY & BROWN BROKEN</u>				
<u>LIME</u>	<u>53</u>	<u>58</u>		
<u>BROWN LIME</u>	<u>58'</u>			

Drilling Firm BOB LARSON - WELL DRILLING Date JUNE 18 - 1971

Address 4038 ALBON RD. MONCLOVA O. Signed Bob Larson
893-3123

*If additional space is needed to complete well log, use next consecutive numbered form.

(134)