

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 395706

County Morrow Township Harmony Section of Township COLUMBUS OHIO
Owner GLEN PUGH Address 2608 GLEN ECHO DR
Location of property CO RD 161 or PHILLIPS Rd OFF OF CO RD 170

CONSTRUCTION DETAILS

Casing diameter 4 1/2 Length of casing 48'
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....
Date of completion July 12-69

BAILING OR (PUMPING TEST) (Specify one by circling)


Test Rate 10 G.P.M. Duration of test 1 hrs.
Drawdown 10 ft. Date July 12-69
Static level-depth to water 10 ft.
Quality (clear, cloudy, taste, odor) no odor
Pump installed by.....

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>8' Ft.</u>
<u>Coale Stone</u>	<u>8'</u>	<u>15'</u>
<u>Sand</u>	<u>15'</u>	<u>18'</u>
<u>BROWN clay</u>	<u>18'</u>	<u>34'</u>
<u>Sand</u>	<u>34'</u>	<u>38'</u>
<u>Lime</u>	<u>38'</u>	<u>41'</u>
<u>Sand</u>	<u>41'</u>	<u>52' 6"</u>
<u>Shoe on bit.</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Ray Bettles
Address Cordington Rt 3

Date July 12-69
Signed Ray

*If additional space is needed to complete well log, use next consecutive numbered form.