

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 395999

County Franklin Township Cedarville Section of Township East
Owner Carl Reese Address RR #1 - Cedarville, O.
Location of property Courtsville Rd - 4 m. E. of Cedarville

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 66'
Type of screen _____ Length of screen _____
Type of pump Sub
Capacity of pump 10 g.p.m.
Depth of pump setting 85'
Date of completion May 10 - 76

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 10 G.P.M. Duration of test 2 hrs.
Drawdown 50 ft. Date May 8 - 76
Static level-depth to water 20 ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by Driller

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>yellow clay</u>	<u>0 Feet</u>	<u>12 Ft.</u>
<u>Blue</u>	<u>12</u>	<u>24</u>
<u>sand</u>	<u>24</u>	<u>28</u>
<u>Blue Clay</u>	<u>28</u>	<u>62</u>
<u>sand</u>	<u>62</u>	<u>64</u>
<u>Limestone</u>	<u>64</u>	<u>88</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Curtis Hughes
Address Box 408 Cedarville, O.

Date May 10 - 76
Signed Curtis Hughes

*If additional space is needed to complete well log, use next consecutive numbered form.

136