ORIGINAL

23e

WELL LOG AND DRILLING REPORT

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 398868

County Darke Township Wayne Section of Township 33

Owner [illegible] Address [illegible]

Location of property 4 mi. South east of [illegible] on Versailles south Eastern RD

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 127

Type of screen None Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion June 15-1970

BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 12 G.P.M. Duration of test 1 hrs.

Drawdown None ft. Date June 15-1970

Static level-depth to water 20 ft.

Quality (clear, cloudy, taste, odor) clear

Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay	0 Feet	65 Ft.
Sand	65	90
Gravel	90	105
Clay	105	111
Gravel	111	127
Water	127	

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



Drilling Firm Willard Bulcher Date June 15-1970

Address R.R. Versailles Ohio Signed Willard Bulcher

*If additional space is needed to complete well log, use next consecutive numbered form.

119