

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 399455

County Delaware Township Genoa Section of Township _____
Owner R. P. Patten Address 6396 Worthington Rd
Location of property Same

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST (Specify one by circling)	
Casing diameter <u>6"</u>	Length of casing <u>70'</u>		Test Rate <u>20</u> G.P.M.	Duration of test <u>3</u> hrs.
Type of screen <u>Perf.</u>	Length of screen <u>4'</u>		Drawdown <u>5'</u>	Date <u>Nov-1971</u>
Type of pump <u>Owner</u>			Static level-depth to water <u>45</u> ft.	
Capacity of pump _____			Quality (clear, cloudy, taste, odor) <u>Clear</u>	
Depth of pump setting _____			Pump installed by _____	
Date of completion _____				
WELL LOG*			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
<u>Clay</u>	<u>0 Feet</u>	<u>60 Ft.</u>	N. <u>Freeman Rd.</u> W. <u>Worthington Rd.</u> E. <u>Africa Rd.</u> S.	
<u>Sand</u>	<u>60</u>	<u>65</u>		
<u>Gravel</u>	<u>65</u>	<u>70</u>		

Drilling Firm Lehman Drilling Date 12/22/71
Address 11143 Fancher Rd. Signed James

*If additional space is needed to complete well log, use next consecutive numbered form.

LOCATED