

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 400609

24e

County PIEDMONT Township SOMERS Section of Township 29

Owner WM. WATKINS Address R R CAMDEN, OHIO

Location of property CORNER OF STEPHANS-YOUNG RD + SWAN BEATTY RD.

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 41'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion DEC 8, 1971

BAILING OR PUMPING TEST (Specify one by circling)

Test Rate 10 G.P.M. Duration of test 2 hrs.
Drawdown 11 ft. Date DEC 8, 1971
Static level-depth to water 18' ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>BRONN CLAY</u>	<u>0 Feet</u>	<u>12 Ft.</u>
<u>GREY CLAY</u>	<u>12</u>	<u>21</u>
<u>GRAVEL</u>	<u>21</u>	<u>41</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

1200 SWAN N.

SWAN BEATTY RD

W. X S.

STEPHANS-YOUNG RD.

Drilling Firm BACH BYOS.
Address CAMDEN, OHIO

Date DEC 8, 1971
Signed Elmer Bach

*If additional space is needed to complete well log, use next consecutive numbered form.