53

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 401133

County Columbiana Township Washington Section of Township 6

Owner William R. Brott Address R.D. #1. Salisbury Rd.

Location of property (State Rt. 39) ½ mi. South of Inter. Sec. of Rt. 39 + 776 Salisbury Rd.

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 29

Type of screen – Length of screen –

Type of pump Submersible

Capacity of pump 10 G.P.M.

Depth of pump setting 108

Date of completion 5-17-73

BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 7 G.P.M. Duration of test 1 hrs.

Drawdown 62 ft. Date 5-11-73

Static level-depth to water 50 ft.

Quality (clear, cloudy, taste, odor) Clear

Pump installed by Driller

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Shale yellow	0 Feet	10 Ft.
Shale gray	10	35
Slate black	35	52
Lime-stone	52	54
Shale dark	54	118
Water 77'		

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



LOCATED

Drilling Firm H. C. Cope Date 5-23-73

Address Box 142 Lisbon O Signed H. C. Cope

*If additional space is needed to complete well log, use next consecutive numbered form.

46-B