WELL LOG AND DRILLING REPORT

ORIGINAL

94

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 402687

County Wood Township Montgomery Section of Township

Owner Mrs. Lucile Huff Address Risingsun Ohio

Location of property North end of Risingsun Ohio

CONSTRUCTION DETAILS

Casing diameter 4½ Length of casing 41

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion Dec. 3, 1970

BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 26 G.P.M. Duration of test 2 hrs.

Drawdown 0 ft. Date Dec 3, 1970

Static level-depth to water 8 ft.

Quality (clear, cloudy, taste, odor) Clear

Pump installed by Owner

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay & gravel	0 Feet	3 Ft.
Broken lime	3	38
Blue lime	38	80
White lime	80	98
		98

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



Drilling Firm Elmer Stahl & Son Date Dec. 3, 1970

Address RR#1 Kansas Ohio Signed Ralph E. Stahl

94

LOCATED

*If additional space is needed to complete well log, use next consecutive numbered form.