

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 404888

County Crawford Township Vernon Section of Township _____

Owner Donald Stone Address _____

Location of property 1 mile north of 96 on state Route 598

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)


Casing diameter 4 1/4 Length of casing 52' Test Rate 8 G.P.M. Duration of test 2 1/2 hrs.
Type of screen _____ Length of screen _____ Drawdown 36 ft. Date Aug. 30, 1974
Type of pump _____ Static level-depth to water 8 ft.
Capacity of pump _____ Quality (clear, cloudy, taste, odor) clear
Depth of pump setting _____ no odor
Date of completion Aug. 28, 1974 Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay Loam</u>	<u>0 Feet</u>	<u>2 Ft.</u>
<u>Yellow Clay</u>	<u>2</u>	<u>12</u>
<u>Blue clay</u>	<u>12</u>	<u>30</u>
<u>Dry Sand & Gravel</u>	<u>30</u>	<u>50</u>
<u>Water Bearing Gravel</u>	<u>50</u>	<u>53</u>

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Justice Drilling
Address Rt #1 Plymouth

Date Sept. 3, 1974
Signed Arthur Justice 24

*If additional space is needed to complete well log, use next consecutive numbered form.