

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

186
No. 407726

County MEDINA Township GRANGER Section of Township _____
Owner DOYLE QUARRELS Address 1386 N. MEDINA LINE RD.
Location of property 4925 STATE RD. MEDINA

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)

Casing diameter 6" Length of casing 102'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion SEPT. 6, 1972
Test Rate 7 G.P.M. Duration of test 4 hrs.
Drawdown 60 ft. Date SEPT. 6, 1972
Static level-depth to water 35 ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

CLAY + GRAVEL	0 Feet	20 Ft.
GRAY CLAY	20	62
SAND + GRAVEL	62	102

WATER 102'

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N. 1386 N. MEDINA LINE RD.
W. STATE RD. 18 E.
1145
102'
143'
S.

Drilling Firm Boreman Drilling
Address 402 W. Main St.
Lagrange, Ohio

Date SEPT. 6, 1972
Signed B. H. Boreman

*If additional space is needed to complete well log, use next consecutive numbered form.

LOCATED
225