

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 408167

County Fairfield Township Violet Section of Township _____

Owner Bob Anderson Address _____

Location of property South Saylor Road Pickerington Ohio

CONSTRUCTION DETAILS

Casing diameter 5 1/2 Length of casing 59 Ft.
Type of screen Pipe Perforated Length of screen 2'
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion May 1 - 1971

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 8 G.P.M. Duration of test 3 hrs.
Drawdown 3 ft. Date May 1971
Static level-depth to water 280 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Yel Clay</u>	<u>0 Feet</u>	<u>5 Ft.</u>
<u>Gray Clay</u>	<u>5</u>	<u>22 -</u>
<u>Gray Hard Pan</u>	<u>22</u>	<u>54</u>
<u>Clean Gravel</u>	<u>54</u>	<u>59</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm R. H. Goodwin
Address 1455 Striebel Rd.

Date May 1971
Signed R. H. Goodwin

*If additional space is needed to complete well log, use next consecutive numbered form.

253
LOCATED
253