

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 408987

County MERCER Township CENTER Section of Township _____

Owner DOYLE BALLANGER Address R4 CELINA

Location of property 1 1/2 MI N. OF ST. RT 33 ON CELINA MENDON RD

CONSTRUCTION DETAILS

Casing diameter 4 Length of casing 29

Type of screen _____ Length of screen _____

Type of pump _____

Capacity of pump _____

Depth of pump setting _____

Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)

Test Rate 21 G.P.M. Duration of test 1 hrs.

Drawdown 8 ft. Date 5-26-73

Static level-depth to water 10 ft.

Quality (clear, cloudy, taste, odor) _____


Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>CLAY</u>	<u>0 Feet</u>	<u>23 Ft.</u>
<u>ROCK</u>	<u>23</u>	<u>92</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm John J. Fisher

Address R1 Coldwater

Date 5-26-73

Signed John J. Fisher

*If additional space is needed to complete well log, use next consecutive numbered form.