

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 409033

County JACKSON Township MADISON Section of Township 18

Owner DAVID HALE Address R2 OAK HILL O.

Location of property COLUMBIAN R.D.

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 45-6
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 1 G.P.M. Duration of test 12 hrs.
Drawdown 2 ft. Date JULY 21 1971
Static level-depth to water 12 ft.
Quality (clear, cloudy, taste, odor) X
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>SHALE</u>	<u>0 Feet</u>	<u>17 Ft.</u>
<u>SAND</u>	<u>17</u>	<u>42</u>
<u>GRAY ROCK</u>	<u>42</u>	<u>49</u>
<u>SHALE ROCK</u>	<u>49</u>	<u>50</u>
<u>ROCK</u>	<u>50</u>	<u>65</u>
<u>SHALE</u>	<u>65</u>	<u>70</u>
<u>WATER</u>	<u>48</u>	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Phil Shaddy
Address OAK HILL O.

Date JULY 21 1971
Signed Phil Shaddy

*If additional space is needed to complete well log, use next consecutive numbered form.