

LOCATED

WELL LOG AND DRILLING REPORT

NO. 40912

County Wood Township Hiddletton Section of Township 21
 Owner Clarence Asmus Address Haskins, O
 Location of property 500' W. of Haskins

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4 1/4 Length of casing 44 Pumping rate 5 G.P.M.
 Type of screen _____ Length of screen _____ Duration of test 1 hrs.
 Type of pump _____ Drawdown 44 ft. Date 6-2-18
 Capacity of pump _____ Developed capacity _____
 Depth of pump setting _____ Static level - depth to water 16 ft.
 Date of completion _____ Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formation
 top dirt + yel. clay
 bl. clay
 hard pan
 coarse gr.

From

To

0

18

32

42

44

N.

W.

E.

LIBERTY HI Rd