

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 409968

K✓
(11)

County Albans Township Dover Section of Township 10
Owner Robert Roberts Address Mellfield Ohio
Location of property Mellfield

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)

Casing diameter 5 Length of casing 51
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion July 27

Test Rate _____ G.P.M. Duration of test 2 hrs.
Drawdown 8 ft. Date July 27
Static level-depth to water 10 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

Surface	0 Feet	2 Ft.
sand & Gravel	2	11
Blue Mud	11	35
quick sand	35	46
water & sand	43	51 1/2

N.

across creek near
water office

W.

R7

13

E.

S.

Drilling Firm H. Esterling
Address 226 Murray Bldg

Date July 27 1971
Signed Delvin Esterling

*If additional space is needed to complete well log, use next consecutive numbered form.

A21