

WELL LOG AND DRILLING REPORT

ORIGINAL

42 ✓

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 409970

County Athens Township Dover Section of Township 21
Owner Sunday Creek Address Cary Ohio
Location of property Baley Run

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)


Casing diameter <u>5</u> Length of casing <u>23</u>	Test Rate.....G.P.M. Duration of test..... <u>2</u> hrs.
Type of screen..... Length of screen.....	Drawdown.....ft. Date <u>Dec 1</u>
Type of pump.....	Static level-depth to water..... <u>14</u> ft.
Capacity of pump.....	Quality (clear, cloudy, taste, odor) <u>Clear</u>
Depth of pump setting.....	
Date of completion <u>Dec 1</u>	Pump installed by.....

WELL LOG*

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Surface</u>	<u>0 Feet</u>	<u>3 Ft.</u>
<u>Blue Mud</u>	<u>3</u>	<u>13</u>
<u>Blue shale</u>	<u>13</u>	<u>26</u>
<u>Lime stone</u>	<u>26</u>	<u>32</u>
<u>Sand Rock</u>	<u>32</u>	<u>38</u>
<u>White shale</u>	<u>38</u>	<u>47</u>
<u>Water shale</u>	<u>47</u>	<u>60</u>

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm DL Esterling
Address 226 Murray City

Date Dec 1 1971
Signed Devin Esterling

*If additional space is needed to complete well log, use next consecutive numbered form.

23