

WELL LOG AND DRILLING REPORT

ORIGINAL ☒

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 409972

County Athens Township Ames Section of Township 87
Owner Ernest W Burchfield Address Amesville Ohio
Location of property R. 9.1.

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 33
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion Dec 23

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate _____ G.P.M. Duration of test 2 hrs.
Drawdown _____ ft. Date Dec 23
Static level-depth to water 20 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Surface	0 Feet	3 Ft.
yellow clay	3	32
sand stone	32	38
limestone	38	42
white shale	42	50
sand stone	50	60

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm P L Easterling
Address 226 Murray St

Date Dec 23 1971
Signed Delphin Easterling

*If additional space is needed to complete well log, use next consecutive numbered form.