

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 415352

152 ✓

County Clark Township Pike Section of Township 23
Owner Norman Filburn Address New Carlisle
Location of property 1 mi north of Ballintine Pike

CONSTRUCTION DETAILS

Casing diameter 5 1/8 Length of casing 158
Type of screen _____ Length of screen _____
Type of pump Submersible
Capacity of pump 10
Depth of pump setting 1
Date of completion 145

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 20 G.P.M. Duration of test _____ hrs.
Drawdown 120 ft. Date Oct. 20 70
Static level-depth to water 25 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by Brunner

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>clay</u>	<u>0 Feet</u>	<u>10 Ft.</u>
<u>" Gravel mix</u>	<u>10</u>	<u>120</u>
<u>sand.</u>	<u>120</u>	<u>152</u>
<u>gravel</u>	<u>152</u>	<u>158</u>
<u>gas from 77 to 110</u>		
<u>Water Sand. 120</u>		
<u>Water 158</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Brunnerwell Shallow
Address Tyros city

Date Oct. 20 1970
Signed Donald H. Brunner

*If additional space is needed to complete well log, use next consecutive numbered form.