

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 415358

County Miami Township Bethel Section of Township _____

Owner Viola Tyson Address Wright Brandt Rd

Location of property 4 mi. South of Rt 570 on Wright Brandt Rd

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)

Casing diameter 5 1/2 Length of casing 25
Type of screen _____ Length of screen _____
Type of pump Jet.
Capacity of pump 600 GPM
Depth of pump setting 123
Date of completion Nov. 1970

Test Rate 2 G.P.M. Duration of test _____ hrs.
Drawdown 125 ft. Date Nov. 70
Static level-depth to water 23 ft.
Quality (clear), cloudy, taste, odor)
Pump installed by Brenner

WELL LOG*

SKETCH SHOWING LOCATION 424

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

2 Ft.

Chg
Limestone
Shale

2

95

95

125


Water 30 ft.

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.



LOCATED

(142)

Drilling Firm Brenner Well Drilling
Address type city

Date Nov. 11 1970
Signed Donald H. Brenner

*If additional space is needed to complete well log, use next consecutive numbered form.