

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 417104

County Trimble Township Bloomfield Section of Township SW
Owner Jesse Sadder Address RD #1 N Bloomfield O
Location of property on W side of SR 45 1/2 mi S of SR 87

CONSTRUCTION DETAILS

Casing diameter 5 1/2 Length of casing 76
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 20 G.P.M. Duration of test _____ hrs.
Drawdown ALL ft. Date July 20 71
Static level-depth to water 28 ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>yellow clay</u>	<u>0 Feet</u>	<u>8 Ft.</u>
<u>Blue clay</u>	<u>8</u>	<u>25</u>
<u>Grey sand gravel & water</u>	<u>25</u>	<u>40</u>
<u>Grey sand gravel & clay</u>	<u>40</u>	<u>76</u>
<u>Light Shale</u>	<u>76</u>	<u>84</u>
<u>returns to 28 ft at</u>		
<u>approx 16 PM</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Newbury Drilling Date Oct 30, 1971
Address RD #1 Bristolville Ohio Signed Fred Newbury

*If additional space is needed to complete well log, use next consecutive numbered form.